

15This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**

09767925-012301  
TOE210"52679260





Figure 1

DP-300566  
2/5

Air Atmosphere

Disk Samples  
1144 Cofred Electrodes

Normalized Current Density  
Initial and Aged




Disk Samples  
I144 Cofired Electrodes

DP-300566  
3/5

Air Atmosphere

DC Volume Resistivity  
Initial and Aged




DELPHI 3262960

DP-300566

4/5

Zirconia Body Electrode Resistivity  
Stability Comparison  
by AC Complex Impedance Measurements



~~Legend:~~

- ~~△ C9 1510C~~
- ~~□ C4 1510C~~
- ~~● C5 1450C~~




Figure 5

09767935 012301  
T08270 52629260